

LDEO New Zealand Data Upload Notes: Version 1

Andrew Barclay 9/27/15

1. APGs (HDH and BKO)

5 Trawl-resistant LDEO BPRs (LBPR1-5); 5 UTIG BPRs (TXBP1-5); 7 LDEO OBSs with internal APGs. All 17 instruments had the same datalogger design and software. Pressure channel (**HDH**) ran at 100 sps; temperature channel (**BKO**) ran at 12.5 sps. Pressure transducer ranges varied. Stations are spread across two DMC network codes: 8F and YH.

Temperature units in miniseed are in millidegrees C. Pressure units in miniseed are 0.01 Pa and the estimated pressure at the surveyed depth in Pa has been subtracted to fit the data into miniseed. (This is why the pressure data disappears during deployment and recovery for some of the deeper sites.) At some point, this information will be moved into a Seed coefficient response blockette, but for now, the subtracted (also in Table 1) pressure is entered in the Seed channel comments.

| Site | Network | Drift, ms | Notes | Pressure correction (Pa) |
|-------|---------|-----------|---|--------------------------|
| LBPR1 | 8F | 67 | | 884549 |
| LBPR2 | 8F | -167 | | 894591 |
| LBPR3 | 8F | -130 | | 834343 |
| LBPR4 | 8F | -170 | | 894591 |
| LBPR5 | 8F | -- | No final clock sync: recovered by dragging | 874508 |
| LOBS1 | YH | -114 | | 10082420 |
| LOBS4 | YH | -- | No final clock sync | 34643548 |
| LOBS5 | YH | -51 | | 23808938 |
| LOBS6 | YH | -19 | | 18908762 |
| LOBS8 | YH | -216 | | 6638239 |
| LOBS9 | YH | -46 | | 14731563 |
| LOB10 | YH | -- | No final clock sync | 14601025 |
| TXBP1 | 8F | -88 | | 36079460 |
| TXBP2 | 8F | -244 | | 7923531 |
| TXBP3 | 8F | -72 | | 10745149 |
| TXBP4 | 8F | -13 | | 14269661 |
| TXBP5 | 8F | -210 | | 12612839 |

Table 1. APG sites, network codes, and CSAC clock drifts, and miniseed pressure correction. Positive drift means there are more counts between the sync times than the nominal clock count rate (1000/s) gives, i.e., clock is fast.

The HDH/BKO data at the DMC are all time-corrected assuming linear drift, except for LBPR5, LOBS4, and LOB10, which had no final clock sync and for which the data quality flag in the miniseed headers is set. All APGs had CSAC atomic clocks that gave very low drift rates, indicating that the maximum timing error on these three sites is probably 250 ms at the end of the experiment.

| Site | HDH start | HDH end | HDH | BKO | Notes |
|-------|-----------|---------|---|-----|---------------------|
| LBPR1 | 2014132 | 2015172 | OK | OK | |
| LBPR2 | 2014132 | 2015172 | OK | OK | |
| LBPR3 | 2014132 | 2015172 | OK | OK | |
| LBPR4 | 2014133 | 2015172 | OK | OK | |
| LBPR5 | 2014133 | 2015180 | OK | OK | Dragged up |
| LOBS1 | 2014134 | 2015172 | OK | OK | |
| LOBS4 | 2014137 | 2015088 | 4-h spikes appear 2015081 and become stronger and more frequent to end (HDH and BKO); final time sync bad. Data stop early. | | |
| LOBS5 | 2014135 | 2014155 | HDH degraded and fell apart 2014155, consistent with observed leak; BKO seems OK to recovery (2015173) | | |
| LOBS6 | 2014137 | 2015177 | OK | OK | HDH=0 for first 48h |
| LOBS8 | 2014134 | 2015177 | OK | OK | |
| LOBS9 | 2014131 | 2015174 | OK | OK | |
| LOB10 | 2014131 | 2015152 | ~4-h Spikes appear 2015144; increase in strength and incidence towards end (HDH and BKO); final time sync bad. Data stop early. | | |
| TXBP1 | 2014132 | 2015178 | OK | OK | Corroded sensor |
| TXBP2 | 2014137 | 2015024 | Running on deck for 3 days before deployment. 2015001, HDH starts to get bumps and spikes. Both channels end suddenly in garbage at 2015024. Corroded sensor. | | |
| TXBP3 | 2014132 | 2014286 | Bumps seen in HDH from start; associated with 0.8 degree drop-offs in BKO. Both channels end suddenly in garbage at 2014286. Corroded sensor. | | |
| TXBP4 | 2014132 | 2014252 | Data start on seafloor at 2014132. Both channels end suddenly in garbage at 2014252. Corroded sensor. | | |
| TXBP5 | 2014131 | 2015066 | Both channels end suddenly in garbage at 2015066. Corroded sensor. | | |

Table 2. Preliminary APG performance evaluation.

2. Seismometer channels

Channels **HHZ**, **HH1**, **HH2**: Trillium Compacts sampled at 100 sps. Seismometer responses are given in seed headers. Instruments included an experimental hydrophone channel (**EDH**), some of which appeared to work. However, **EDH** responses at DMC are nominal for now (actually, borrowed from WHOI).

| Site | EDH | APG ? | HH* Performance and power notes |
|-------|-----------|-------|--|
| LOBS1 | OK | Yes | All stop 2014329:08:30.000. Did get ratty in the hours up to then. Datalogger ran until end and Seascan clock was OK. Startup/main analog depleted; digital OK |
| LOBS2 | Bad | No | All stop 2014325:23:26:20. Did get ratty in the hours up to then. Datalogger ran until end and Seascan clock was OK. Startup/main analog depleted; digital OK |
| LOBS3 | Good | No | All stop 2014286. Good up until then. Batteries OK on recovery |
| LOBS4 | n/a | Yes | All bad from start. All stop 2014034:16:32:30 DOA, no tick counts |
| LOBS5 | Flatlined | Yes | Leaked. Probably no usable data. Stopped 2014287. No power info. |

| | | | |
|-------|-----------|-----|---|
| LOBS6 | Flatlined | Yes | Worked. Batteries OK on recovery |
| LOBS7 | OK | No | Worked. Batteries OK on recovery |
| LOBS8 | Good | Yes | Worked. Batteries OK on recovery |
| LOBS9 | Good | Yes | Worked. Digital & analog slightly low |
| LOB10 | Good | Yes | Went bad, then stopped. OK at start. DOA, no tick counts. |

Table 3. Preliminary performance evaluation for seismometers. Three OBSs did not have APGs. Analysis is based on quick inspection of time series alone.

| Site | Drift, s | Style | Seismo clock |
|-------|----------|----------|--------------|
| LOBS1 | 1.212 | Cascadia | Seascan |
| LOBS2 | 0.085 | Cascadia | Seascan |
| LOBS3 | 6.62s | NZ | CSAC |
| LOBS4 | -- | NZ | CSAC |
| LOBS5 | 13.6s | NZ | CSAC |
| LOBS6 | -0.590 | Cascadia | Seascan |
| LOBS7 | -4.6s | Cascadia | CSAC |
| LOBS8 | -1.812 | Cascadia | Seascan |
| LOBS9 | 43s | NZ | CSAC |
| LOB10 | -- | NZ | CSAC |

Table 4. Seismometer clock description and performance. Red drifts are anomalously large and all for OBSs that shared CSAC clocks with APGs.

2.1. OBS performance notes

LOBS1 and LOBS2: Both went to 0 counts after several months. Analog power drained. Suspected cause is Trillium Compact remaining in high-power mode after leveling.

LOBS4 and LOBS10: They also stopped early and had depleted batteries (both digital and analog) on recovery. Not yet resolved. had no reliable final APG syncs either.

LOBS5: Leaked on deployment. Suspect is 12-pin sensor connectors/cables that were difficult to connect.

LOBS4 not uploaded to DMC. No usable data (although the real reason it wasn't uploaded was a mistake in the transcription that wasn't noticed until it was too late). For completeness, the plan is to upload it to the DMC in late October.

2.2. Seismometer timing

Four instruments (LOBS1, LOBS2, LOBS6, LOBS8) used a quartz Seascan clock for the seismometer/hydrophone datalogger, and a CSAC clock for the APG logger. The respective clock drifts were as expected for these instruments, with the Seascan drift an order of magnitude greater than the CSAC drift. Crude cross-correlation (generally a 1-4 h window at the start of each 12 or 24-h period) of the wave loading signal between APG and vertical seismometer (Figure 1) shows that LOBS1 had excellent timing to within 2 samples, or 20 ms. LOBS6 also had low drifts but an apparent mean offset of ~50 ms (the correlation quality was very low for LOBS6) and LOBS8 had a systematic parabolic drift with a peak at 30 ms.

LOBS 4 and LOB10 had no final clock sync, so the DMC data for these instruments are not clock-corrected. The data flags in the miniseed headers are set accordingly.

Some of the other instruments (LOBS 3, 5, 7, 9) shared a single CSAC clock for both APG and seismometer loggers. Although the APG timing was good, the seismometers had unreasonably high clock drifts (for a CSAC a few hundred ms is reasonable; 1 s is average for a Seascan clock over a year). The reason for this is not yet resolved but appears to be a degraded CSAC clock signal that is triggering false or missed counts on the seismometer logger (but not on the APG logger which has a different triggering algorithm).

If the APG timing was good, can the ocean wave signal be used to recover the OBS timing ?

Only partially. LOBS 5 flooded early; and LOBS 3 and 7 were two of the 3 OBSs that had no APGs. For LOBS9, the cross-correlation was successfully applied to the clock-drift-corrected data (i.e., after removing and assumed linear annual drift of 43s for LOBS9). Cross-correlation of the HDH and HHZ channels (0.1-1s) produced lags for which the local scatter was comparable to that of LOBS1. However, the lags are not linear and vary from +/- 0.5 s.

This suggests that for LOBS9, reasonable seismometer timing can be recovered from cross-correlation with the HDH channel, but only locally. Given that the linear correction reduced the timing error by two orders of magnitude (from 43 s to ~400 ms), it is possible that a linear correction to the LOBS3, LOBS5 and LOBS7, (which had lower overall drifts of 6, 13 and 4 s) reduces the timing error to 60, 130 and 40 ms.

For these four sites, the data at the DMC were clock-drift corrected for linear drift.




Figure 1. Lags between HDH and HHZ for ocean waves for five instruments. (LOBS1) good agreement between atomic CSAC and quartz Seascan clocks; (LOBS6) poorer agreement with possible ~ 50 ms offset but no apparent drift difference; (LOBS8) very good agreement, systematic max drift of ~ 30 ms; (LOBS9) good lag estimates but large, nonlinear variation for same CSAC clock; (LOB10) no coherence. In all cases, the linear clock-drift correction made before cross-correlating.