

经纬仪导线计算

线号

第

页

~~座标换经纬度~~

LINEEC

TIB-10

COORDINATE CONVERSION
TABLE

李绿梅

LINEE
LINEEc
LINEF

装

订

线

LINEC

TIB-10

①

XY CHANGE BL
 PN: 103650 146
 L1= 93
 L2= 0
 X1= 3363410.556
 Y1=16288022.28
 B= 30.221713
 L= 90.47422665

PN: 108772.96
 L1= 93
 L2= 0
 X1= 3359020.69
 Y1=16290661.38
 B= 30.19563367
 L= 90.49241854

350.2184

十 算

第 页

工 区:

PN: 103952.65
 L1= 93 158.106
 L2= 0
 X1= 3363151.22
 Y1=16288178.2
 B= 30.22088132
 L= 90.47482903

PN: 110108.72
 L1= 93
 L2= 0
 X1= 3357876.05
 Y1=16291349.29
 B= 30.19196207
 L= 90.49507382

404.3488

PN: 104893.66
 L1= 93 195.7464
 L2= 0
 X1= 3362344.878
 Y1=16288663.01
 B= 30.21429537
 L= 90.48070183

PN: 110889.75
 L1= 93
 L2= 0
 X1= 3357206.77
 Y1=16291751.51
 B= 30.18581518
 L= 90.5006261

435.59

PN: 105771.28
 L1= 93 230.0512
 L2= 0
 X1= 3361592.847
 Y1=16289115.17
 B= 30.21188352
 L= 90.48244826

PN: 111350
 L1= 93
 L2= 0
 X1= 3356812.37
 Y1=16291988.53
 B= 30.18455002
 L= 90.50154074

454

PN: 106491.42
 L1= 93 257.6560
 L2= 0
 X1= 3360975.757
 Y1=16289486.19
 B= 30.20590437
 L= 90.48388111

~ 贝
 略 图



测线号 点 或 点

填表者
检查者

经纬仪导线计算

线号

第

页

LIN EEC

TIB-10

装

线

2

105200
 X= 3362082.37
 Y= 16288820.85
 H= 4383.3

105175
 X= 3362103.79
 Y= 16288807.97
 H= 4384.7

105150
 X= 3362125.21
 Y= 16288795.09
 H= 4386.3

105125
 X= 3362146.63
 Y= 16288782.21
 H= 4388.3

105100
 X= 3362168.05
 Y= 16288769.33
 H= 4389.8

105075
 X= 3362189.48
 Y= 16288756.45
 H= 4391.6

105050
 X= 3362210.90
 Y= 16288743.57
 H= 4392.9

105025
 X= 3362232.32
 Y= 16288730.69
 H= 4395.9

105000
 X= 3362253.74
 Y= 16288717.81
 H= 4396.7

104975
 X= 3362275.16
 Y= 16288704.93
 H= 4398.7

104950
 X= 3362296.59
 Y= 16288692.05
 H= 4400.5

104925
 X= 3362318.01
 Y= 16288679.17
 H= 4402.4

104900
 X= 3362339.43
 Y= 16288666.29
 H= 4404.0

104875
 X= 3362360.87
 Y= 16288653.40
 H= 4406.1

104850
 X= 3362382.29
 Y= 16288640.52
 H= 4407.8

104825
 X= 3362403.71
 Y= 16288627.64
 H= 4409.6

105600
 X= 3361739.61
 Y= 16289026.93
 H= 4360.0

105575
 X= 3361761.04
 Y= 16289014.05
 H= 4361.1

105550
 X= 3361782.46
 Y= 16289001.17
 H= 4362.4

105525
 X= 3361803.88
 Y= 16288988.29
 H= 4363.8

105500
 X= 3361825.30
 Y= 16288975.41
 H= 4365.3

105475
 X= 3361846.72
 Y= 16288962.53
 H= 4367.0

105450
 X= 3361868.15
 Y= 16288949.65
 H= 4368.5

105425
 X= 3361889.57
 Y= 16288936.77
 H= 4369.8

105400
 X= 3361910.99
 Y= 16288923.89
 H= 4371.0

105375
 X= 3361932.41
 Y= 16288911.01
 H= 4372.4

105350
 X= 3361953.83
 Y= 16288898.13
 H= 4374.0

105325
 X= 3361975.26
 Y= 16288885.25
 H= 4375.4

105300
 X= 3361996.68
 Y= 16288872.37
 H= 4377.2

105275
 X= 3362018.10
 Y= 16288859.49
 H= 4379.0

105250
 X= 3362039.52
 Y= 16288846.61
 H= 4380.4

105225
 X= 3362060.94
 Y= 16288833.73
 H= 4381.8

106000
 X= 3361396.86
 Y= 16289233.01
 H= 4345.2

105975
 X= 3361418.29
 Y= 16289220.13
 H= 4345.9

105950
 X= 3361439.71
 Y= 16289207.25
 H= 4346.6

105925
 X= 3361461.13
 Y= 16289194.37
 H= 4347.4

105900
 X= 3361482.56
 Y= 16289181.49
 H= 4348.2

105875
 X= 3361503.98
 Y= 16289168.61
 H= 4349.1

105850
 X= 3361525.40
 Y= 16289155.73
 H= 4349.9

105825
 X= 3361546.83
 Y= 16289142.85
 H= 4350.6

105800
 X= 3361568.25
 Y= 16289129.97
 H= 4351.2

105775
 X= 3361589.67
 Y= 16289117.09
 H= 4352.0

105750
 X= 3361611.08
 Y= 16289104.21
 H= 4352.9

105725
 X= 3361632.50
 Y= 16289091.33
 H= 4353.7

105700
 X= 3361653.93
 Y= 16289078.45
 H= 4354.3

105675
 X= 3361675.35
 Y= 16289065.57
 H= 4356.6

105650
 X= 3361696.77
 Y= 16289052.69
 H= 4357.9

105625
 X= 3361718.19
 Y= 16289039.81
 H= 4358.8

2

200

220

240

230

210

经

线号

107400
X= 3360197.19
Y= 16289954.30
H= 4317.5

107375
X= 3360218.61
Y= 16289941.42
H= 4317.5

107350
X= 3360240.04
Y= 16289928.54
H= 4317.7

107325
X= 3360261.46
Y= 16289915.66
H= 4318.0

107300
X= 3360282.88
Y= 16289902.78
H= 4318.4

107275
X= 3360304.31
Y= 16289889.90
H= 4318.6

107250
X= 3360325.73
Y= 16289877.02
H= 4318.9

107225
X= 3360347.15
Y= 16289864.14
H= 4319.2

107425
X= 3360175.77
Y= 16289967.18
H= 4317.2

107450
X= 3360154.34
Y= 16289980.06
H= 4317.0

107475
X= 3360132.92
Y= 16289992.94
H= 4316.6

107500
X= 3360111.50
Y= 16290005.82
H= 4316.3

107525
X= 3360090.08
Y= 16290018.70
H= 4316.2

107550
X= 3360068.65
Y= 16290031.58
H= 4316.1

107575
X= 3360047.23
Y= 16290044.46
H= 4315.9

107600
X= 3360025.81
Y= 16290057.34
H= 4315.6

107625
X= 3360004.38
Y= 16290070.22
H= 4315.2

107650
X= 3359982.96
Y= 16290083.10
H= 4315.1

107675
X= 3359961.54
Y= 16290095.98
H= 4315.1

107700
X= 3359940.11
Y= 16290108.86
H= 4315.0

107725
X= 3359918.69
Y= 16290121.74
H= 4314.7

107750
X= 3359897.27
Y= 16290134.62
H= 4314.8

107775
X= 3359875.85
Y= 16290147.50
H= 4314.6

107800
X= 3359854.42
Y= 16290160.38
H= 4314.5

107825
X= 3359833.00
Y= 16290173.26
H= 4313.7

107850
X= 3359811.58
Y= 16290186.14
H= 4313.4

107875
X= 3359790.15
Y= 16290199.02
H= 4313.6

107900
X= 3359768.73
Y= 16290211.90
H= 4313.5

107925
X= 3359747.31
Y= 16290224.78
H= 4313.1

107950
X= 3359725.88
Y= 16290237.66
H= 4312.9

107975
X= 3359704.46
Y= 16290250.54
H= 4312.8

108000
X= 3359683.04
Y= 16290263.42
H= 4312.5

108025
X= 3359661.62
Y= 16290276.30
H= 4312.1

108050
X= 3359640.19
Y= 16290289.18
H= 4312.1

108075
X= 3359618.78
Y= 16290301.93
H= 4312.3

108100
X= 3359597.36
Y= 16290314.81
H= 4311.6

108125
X= 3359575.93
Y= 16290327.69
H= 4311.1

108150
X= 3359554.51
Y= 16290340.57
H= 4310.6

108175
X= 3359533.09
Y= 16290353.45
H= 4310.4

108200
X= 3359511.66
Y= 16290366.33
H= 4310.0

装 订 线

5

6

.....
装
.....
订
.....
线
.....

108225
X= 3359490.24
Y= 16290379.21
H= 4309.6

108250
X= 3359468.82
Y= 16290392.09
H= 4309.4

108275
X= 3359447.39
Y= 16290404.97
H= 4309.2

108300
X= 3359425.97
Y= 16290417.85
H= 4309.1

108325
X= 3359404.55
Y= 16290430.73
H= 4308.9

108350
X= 3359383.13
Y= 16290443.61
H= 4308.8

108375
X= 3359361.70
Y= 16290456.49
H= 4308.7

108400
X= 3359340.28
Y= 16290469.37
H= 4308.6

108425
X= 3359318.86
Y= 16290482.25
H= 4308.5

108450
X= 3359297.43
Y= 16290495.13
H= 4308.4

108475
X= 3359276.01
Y= 16290508.01
H= 4308.3

108500
X= 3359254.59
Y= 16290520.89
H= 4308.2

108525
X= 3359233.16
Y= 16290533.77
H= 4308.1

108550
X= 3359211.74
Y= 16290546.65
H= 4308.0

108575
X= 3359190.32
Y= 16290559.53
H= 4307.9

108600
X= 3359168.90
Y= 16290572.41
H= 4307.8

330

340

320
330

128625
X= 3359147.47
Y= 16290585.29
H= 4307.7

108650
X= 3359126.05
Y= 16290598.17
H= 4307.6

108675
X= 3359104.63
Y= 16290611.05
H= 4307.5

108700
X= 3359083.20
Y= 16290623.93
H= 4307.4

108725
X= 3359061.78
Y= 16290636.81
H= 4307.3

108750
X= 3359040.36
Y= 16290649.69
H= 4307.2

108775
X= 3359018.94
Y= 16290662.43
H= 4307.1

108800
X= 3358997.52
Y= 16290675.30
H= 4307.0

108825
X= 3358976.09
Y= 16290688.17
H= 4306.9

108850
X= 3358954.67
Y= 16290701.04
H= 4306.8

108875
X= 3358933.25
Y= 16290713.91
H= 4306.7

108900
X= 3358911.83
Y= 16290726.78
H= 4306.6

108925
X= 3358890.40
Y= 16290739.65
H= 4306.5

108950
X= 3358868.98
Y= 16290752.52
H= 4299.8

108975
X= 3358847.56
Y= 16290765.39
H= 4299.5

109000
X= 3358826.13
Y= 16290778.26
H= 4299.2

109025
X= 3358804.71
Y= 16290791.13
H= 4299.0

109050
X= 3358783.29
Y= 16290804.00
H= 4298.7

109075
X= 3358761.86
Y= 16290816.87
H= 4298.5

109100
X= 3358740.44
Y= 16290829.74
H= 4298.3

109125
X= 3358719.02
Y= 16290842.61
H= 4298.1

109150
X= 3358697.60
Y= 16290855.48
H= 4297.9

109175
X= 3358676.17
Y= 16290868.35
H= 4297.7

109200
X= 3358654.75
Y= 16290881.22
H= 4297.5

109225
X= 3358633.33
Y= 16290894.09
H= 4297.3

109250
X= 3358611.90
Y= 16290906.96
H= 4297.1

109275
X= 3358590.48
Y= 16290919.83
H= 4296.9

109300
X= 3358569.06
Y= 16290932.70
H= 4296.7

109325
X= 3358547.63
Y= 16290945.57
H= 4296.5

109350
X= 3358526.21
Y= 16290958.44
H= 4296.3

109375
X= 3358504.79
Y= 16290971.31
H= 4296.1

109400
X= 3358483.37
Y= 16290984.18
H= 4295.9

370

6

6

109425
 X= 3358461.94
 Y= 16290997.05
 H= 4295°
 109450
 X= 3358440.52
 Y= 16291009.92
 H= 4295°
 109475
 X= 3358419.10
 Y= 16291022.79
 H= 4294.8
 109500
 X= 3358397.67
 300 Y= 16291035.66
 H= 4294.7
 109525
 X= 3358376.25
 Y= 16291048.53
 H= 4294.4
 109550
 X= 3358354.83
 Y= 16291061.40
 H= 4294.2
 109575
 X= 3358333.40
 Y= 16291074.27
 H= 4294°
 109600
 X= 3358311.98
 Y= 16291087.14
 H= 4294°
 109625
 X= 3358290.56
 Y= 16291100.01
 H= 4293.6
 109650
 X= 3358269.14
 Y= 16291112.88
 H= 4293.4
 109675
 X= 3358247.71
 Y= 16291125.75
 H= 4293.3
 109700
 X= 3358226.29
 Y= 16291138.62
 H= 4293.3
 109725
 X= 3358204.87
 300 Y= 16291151.49
 H= 4293.3
 109750
 X= 3358183.44
 300 Y= 16291164.36
 H= 4292.9
 109775
 X= 3358162.02
 Y= 16291177.23
 H= 4292.8
 109800
 X= 3358140.60
 Y= 16291190.10
 H= 4292.7

109825
 X= 3358119.17
 Y= 16291202.97
 H= 4293°
 109850
 X= 3358097.75
 Y= 16291215.84
 H= 4292.6
 109875
 X= 3358076.33
 Y= 16291228.71
 H= 4292.2
 109900
 X= 3358054.91
 Y= 16291241.58
 H= 4292.2
 109925
 X= 3358033.48
 Y= 16291254.45
 H= 4292°
 109950
 X= 3358012.06
 Y= 16291267.32
 H= 4292.8
 109975
 400 X= 3357990.64
 Y= 16291280.19
 H= 4292.6
 110000
 400 X= 3357969.21
 Y= 16291293.06
 H= 4293°
 110025
 X= 3357947.79
 Y= 16291305.93
 H= 4293.1
 110050
 X= 3357926.37
 Y= 16291318.80
 H= 4292.9
 110075
 X= 3357904.94
 Y= 16291331.67
 H= 4292.6
 110100
 X= 3357883.52
 Y= 16291344.54
 H= 4292.4
 110125
 X= 3357862.10
 Y= 16291357.67
 H= 4292.4
 110150
 X= 3357840.68
 Y= 16291370.54
 H= 4292.4
 110175
 X= 3357819.26
 Y= 16291383.41
 H= 4292.1
 110200
 X= 3357797.83
 Y= 16291396.28
 H= 4291.9

110225
 X= 3357776.41
 400 Y= 16291409.15
 H= 4291.6
 110250
 X= 3357754.99
 410 Y= 16291422.02
 H= 4291.7
 110275
 X= 3357733.56
 Y= 16291434.89
 H= 4291.9
 110300
 X= 3357712.14
 Y= 16291447.76
 H= 4291.2
 110325
 X= 3357690.72
 Y= 16291460.63
 H= 4290.8
 110350
 X= 3357669.29
 Y= 16291473.50
 H= 4291.4
 110375
 X= 3357647.87
 Y= 16291486.37
 H= 4291.5
 110400
 X= 3357626.45
 Y= 16291499.24
 H= 4291.3
 110425
 X= 3357605.03
 Y= 16291512.11
 H= 4290.7
 110450
 X= 3357583.60
 Y= 16291524.98
 H= 4290.7
 110475
 X= 3357562.18
 Y= 16291537.85
 H= 4290.2
 110500
 X= 3357540.76
 420 Y= 16291550.72
 H= 4289.8
 110525
 X= 3357519.33
 Y= 16291563.59
 H= 4290°
 110550
 X= 3357497.91
 Y= 16291576.46
 H= 4289.8
 110575
 X= 3357476.49
 Y= 16291589.33
 H= 4289.7
 110600
 X= 3357455.06
 Y= 16291602.20
 H= 4289.5

装
线

10625
 X= 3357433.64
 Y= 16291615.07
 H= 4289.6

10650
 X= 3357412.22
 Y= 16291627.94
 H= 4289.6

10675
 X= 3357390.80
 Y= 16291640.81
 H= 4289.8

10700
 X= 3357369.37
 Y= 16291653.68
 H= 4289.7

10725
 X= 3357347.95
 Y= 16291666.55
 H= 4289.8

10750
 X= 3357326.53
 Y= 16291679.42
 H= 4290.0

110775
 X= 3357305.10
 Y= 16291692.29
 H= 4289.7

110800
 X= 3357283.68
 Y= 16291705.16
 H= 4289.5

110825
 X= 3357262.26
 Y= 16291718.03
 H= 4289.4

110850
 X= 3357240.83
 Y= 16291730.90
 H= 4289.7

110875
 X= 3357219.41
 Y= 16291743.77
 H= 4289.7

110900
 X= 3357197.99
 Y= 16291756.79
 H= 4289.4

110925
 X= 3357176.56
 Y= 16291769.66
 H= 4289.4

110950
 X= 3357155.14
 Y= 16291782.53
 H= 4289.8

110975
 X= 3357133.72
 Y= 16291795.40
 H= 4289.9

111000
 X= 3357112.29
 Y= 16291808.27
 H= 4289.9

111025
 X= 3357090.87
 Y= 16291821.14
 H= 4289.9

111050
 X= 3357069.45
 Y= 16291834.01
 H= 4289.0

111075
 X= 3357048.02
 Y= 16291846.88
 H= 4288.9

111100
 X= 3357026.60
 Y= 16291859.75
 H= 4288.8

111125
 X= 3357005.18
 Y= 16291872.62
 H= 4288.8

111150
 X= 3356983.76
 Y= 16291885.49
 H= 4288.7

111175
 X= 3356962.33
 Y= 16291898.36
 H= 4289.0

111200
 X= 3356940.91
 Y= 16291911.23
 H= 4288.7

111225
 X= 3356919.49
 Y= 16291924.10
 H= 4288.8

111250
 X= 3356898.06
 Y= 16291936.97
 H= 4288.9

111275
 X= 3356876.64
 Y= 16291949.84
 H= 4289.0

111300
 X= 3356855.22
 Y= 16291962.71
 H= 4288.7

111325
 X= 3356833.79
 Y= 16291975.58
 H= 4288.6

111350
 X= 3356812.37
 Y= 16291988.45
 H= 4288.8

算

第 页

8
 7

装

订

线

